


# SM-7-R



## Grundhalter - Aufnahme Typ 2: Zylindrisch mit Mitnahmebohrung

Base holder - type 2: Cylindrical with drive bore / Support de base - type 2: Cylindrique avec trou d'entraînement

| Art. Nr.<br>Item no.<br>Réf. | Bezeichnung<br>Designation<br>Désignation | Maschinentyp<br>Machine type<br>Type de machine | DF | D1 | b | t <sub>max</sub> | B   | C | A  | Drehrichtung<br>Direction of rotation<br>Sense de rotation |
|------------------------------|---|---|----|----|---|------------------|-----|---|----|--|
| 103377                       | SM-7-R                                    | Tornos<br>AS 14                                 | 57 | 16 | 3 | 2,2              | 8,0 | - | 11 | R  |

## Ersatzteile

Spare Parts / Pièces de rechange

| (2) Platte<br>Insert<br>Plaquette | (3) Schraube<br>Screw<br>Vis |                          | (4) Auswuchtteil<br>Balancing insert<br>Plaqu. de balance |                           |
|-----------------------------------|------------------------------|--------------------------|---|---------------------------|
| Bez.<br>Des.<br>Dés.              | Art. Nr.<br>Item no.<br>Réf. | Bez.<br>Des.<br>Dés.     | Art. Nr.<br>Item no.<br>Réf.                              | Bez.<br>Des.<br>Dés.      |
| <a href="#">SMP-06-300..</a>      | 102608                       | <a href="#">S-253545</a> | 103380  | <a href="#">SMAT-06-N</a> |
|                                   | 103602                       | <a href="#">T7</a>       |   |                           |

